

www.evotech-performance.com
SP Connect Sat Nav Bar Clamp
Mount Instruction



For SP Connect mirco stem mount alu Part number #53122 follow instructions 1 - 16

For SP Connect anti vibration module Part number #53135 follow instructions 17 - 31








Kit Contents PRN014677-015147


- A 1 x Upper Mounting Body
- B 1 x Lower Mounting Body
- © 1 x Mounting Plate
- ① 1 x SP Connect Mounting Plate
- **E** 1 x M5 Nyloc Nut
- © 2 x M4 x 25mm Caphead Bolts
- © 2 x O-ring
- (H) 2 x Spacer
- ① 2 x M5 x 10mm Caphead Bolts


























































Kit Contents PRN014677-015147


- A 1 x Upper Mounting Body
- B 1 x Lower Mounting Body
- © 1 x Mounting Plate
- D 1 x SP Connect Mounting Plate
- **E** 1 x M5 Nyloc Nut
- © 2 x M4 x 25mm Caphead Bolts
- © 2 x O-ring
- (H) 2 x Spacer
- ① 2 x M5 x 10mm Caphead Bolts






























26





















It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced





www.evotech-performance.com