



www.evotech-performance.com Yamaha Tracer 9 Garmin Sat Nav Mount

























































































18 Installation Instructions . Merce Contract


































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced

PERFORMANCE



www.evotech-performance.com