


www.evotech-performance.com Multistrada V4 Exhaust Hanger Kit






Harris and



60.

355






1.00





0-0-Repeat **Both Sides**























 \cap













It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



www.evotech-performance.com