




Thank you for purchasing a ZTechnik Product. Please read these instructions carefully and thoroughly before beginning work. Dealers if installing this windshield for a customer please give them this manual. It contains information needed to properly maintain and use this product.



KIT CONTAINS ONE OF THE FOLLOWING WINDSCREENS

Item	Description	Qty.
1	Z2440, Windscreen Tall Light Tint	1
or	Z2441, Windscreen Sport, Dark Tint	1
BAG 1010, Contained in all Kits		
2	75-762423-000, Gasket	1

TOOL REQUIRED:

5mm Hex Key

PREPARATION

1. Remove the stock windshield. Hardware will be reused.

INSTALLATION


1. Position supplied gasket between inside surface of the VStream windshield and motorcycle fairing. Install windshield using stock screw assemblies. **5mm Hex Key**

2. Tighten Screws firmly, do not overtighten.

VStream® windshield patent no. 7,387,328

MAINTENANCE To clean the screen, wash with a clean soft cloth, plenty of warm water and if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. **Paint, glue residue or grease removal:** Moisten cotton with Naphtha or Turpentine followed by a wash as above. National Cycle Shield Wash™ makes a good daily cleaner and comes with a handy travel size bottle. N1401 Shield Wash is safe for helmet visors.

Do not clean polycarbonate in hot sun or high temperatures. Do not clean the screen with glass cleaners. Do not use rain protective products on the screen. Do not allow brake fluid, alcohol, or strong solvents to contact the screen.



ZTechnik 3-Year Limited Warranty Register your windshield on Line at: www.ZTechnik.com

ZTechnik hereby warrants to the original registered owner of a ZTechnik polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windshield. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all ZTechnik windshields.

Visit www.ZTechnik.com for further details or call or write ZTechnik / PO Box 158 / Maywood, IL 60153 / 708-3430400