


## Ducati Panigale SP Connect Sat Nav Mount




# For SP Connect mirco stem mount alu Part number #53122 follow instructions 1 - 18

For SP Connect anti vibration module Part number #53135 follow instructions 19 - 33









































C

















































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced








































































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced





www.evotech-performance.com