



www.evotech-performance.com Suzuki GSX-S1000 GT Garmin Sat Nav Mount






























PERFORMANCI










































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



www.evotech-performance.com