



**EVOTECH**®  
P E R F O R M A N C E

[www.evotech-performance.com](http://www.evotech-performance.com)

Generic Bar Clamp

SP Connect Sat Nav Mount Instruction




For SP Connect mirco stem mount alu Part number #53122


For SP Connect anti vibration module Part number #53135




## Kit Contents

- (A) 1 x Pivot Plate
- (B) 1 x Left Hand Arm
- (C) 1 x Right Hand Arm
- (D) 1 x SP Connect Plate
- (E) 1 x M5 Nylock Nut
- (F) 1 x M6 x 16 Countersunk Screw
- (G) 2 x Spacer
- (H) 2 x M5 x 12 Caphead Bolt
- (I) 2 x M8 Caphead Bolt
- (J) 2 x M5 x 35mm Caphead Bolt
- (K) 2 x Lobe Screw
- (L) 2 x M5 x 10mm Caphead Bolt







Repeat For  
Both Arms




Repeat For  
Both Arms



















**Do Not Fully Tighten**





















For SP Connect anti vibration module Part number #53135






Supplied with  
#53135


E






Repeat  
Both Sides










Caution

Fully  
Tighten





## ESSENTIAL CHECKS



It is recommended that periodic inspections are made to ensure that all bolts are tightened to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced



**EVOTECH**®  
P E R F O R M A N C E

[www.evotech-performance.com](http://www.evotech-performance.com)