


www.evotech-performance.com Ducati DesertX Quadlock Sat Nav Mount






Repeat Both Sides




Repeat Both Sides

















































ant production in
























































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced

PERFORMANCE



www.evotech-performance.com